


Barrier Components Ltd Unit 8 Dolphin Point Dolphin Way Purfleet Essex RM19 1NR

T: 01708 891 515 F: 01708 891 516 www.barrier-components.co.uk


HGT-100 & 200 notching details

HGT-100 - hydraulic patch fitting

glass notching options for standard clearances under door



There are two different glass cut outs for the HGT-100, resulting in different bottom clearances. You can opt for the reduced clearance gap if the floor condition is good and level.



GCC would recommend the customer cuts **60mm** depth (bottom gap 12mm) to allow for most floor condition.

HGT-200 - top patch fitting

glass notching options for standard clearances over door

